# **Notice to Suppliers**



## **Out of Sequence Working: Supplier Self-Assessments**

Originator: Leslie Wanick French NTS Number: NTS 633

Job Title: Chief of ME Issue: 1

**Business Unit:** Aerospace Procurement **Date:** 8 August 2025

For the attention of Quality Directors or similar role

### Scope/Applicability:

All Aerospace Suppliers

#### Dear Supplier Partner,

Rolls-Royce would like to reinforce the importance of ensuring work is not undertaken out of sequence. While Rolls-Royce has not been involved in or affected by any recent events, we would like to take this opportunity to revisit the controls in our own supply chain. We wish to ensure that suppliers continue to work in sequence, follow all specified quality processes and deliver products that confirm to all relevant engineering standards.

#### **Action Required:**

From the date of this NTS onwards, Rolls-Royce requires suppliers to complete a self-assessment to ensure the risks associated with non-standard, out-of-sequence, and/or travelled work are being managed appropriately. Suppliers must:

- 1. Visit the SDRO Portal and access Supplier Quality Bulletin No: 25-001.
- Complete the listed self-assessments as requested by Rolls-Royce.
- 3. If a supplier finds any instance of non-compliance, please raise this as a Notice of Escape following the recently updated processes detailed in NTS630 and NTS631.

If you have any questions, please contact your usual Rolls-Royce Quality point of contact.

Thank you for your continued cooperation.

NTS Category:

Quality

David Halpin

VP Quality & HSE - Aerospace Procurement

© Rolls-Royce August 2025 Page 1 of 1 NTS 633 Issue 1